



**Watershed Watch
Base Monitoring Survey Report**

Date and Time: 11-8-22 2:30pm

Location: Cypress Cove Park

Observers: Anna and Cherith

Weather: 68 degrees fahrenheit, sunny, and windy

Rainfall Past 24 hours: 0"

I. In-Creek Conditions

- A. Water: Brownish water, murky, high turbidity.
- B. Creek Bottom: The creek bottom was not visible due to turbidity.
- C. Vegetation: Spartina grass and Cypress Trees.
- D. Pipes Present: No

II. Creek Corridor Conditions

- A. Creek Bank: Banks are stable with vegetation.
- B. Runoff: Runoff from docks and nearby apartment buildings.
- C. Corridor: Public park with recreational access. Wetlands present and new construction nearby. Apartments nearing completion.
- D. Litter: Sparse.

III. Wildlife

- A. Biodiversity: Birds, fish, and minnows.
- B. Endangered Species: None present.

IV. Water Quality Data

- A. DO – 59.3%
- B. DO ppm – 5.10
- B. pH – 6.99
- C. Temp – 21.4 degrees celsius

Corridor:



Water Surface/Creek Bank:

