



**Watershed Watch  
Base Monitoring Survey Report**

Date and Time: 11-8-22 1:48pm

Location: Sturgeon Creek

Observers: Anna and Cherith

Weather: Sunny, Windy, 68 degrees fahrenheit

Rainfall Past 24 hours: 0"

**I. In-Creek Conditions**

- A. Water: Surfwater was brown and muddy.
- B. Creek Bottom: Low visibility, muddy, and high turbidity.
- C. Vegetation: Spartina grass and Pine trees.
- D. Pipes Present: No.

**II. Creek Corridor Conditions**

- A. Creek Bank: Banks are somewhat stable with vegetative cover.
- B. Runoff: Runoff from road.
- C. Corridor: Wetlands present, road and bridge nearby.
- D. Litter: Sparse.

**III. Wildlife**

- A. Biodiversity: Minnows.
- B. Endangered Species: None present.

**IV. Water Quality Data**

- A. DO – 97.7%
- B. DO ppm – 8.4
- B. pH – 7.37
- C. Temp – 21.4 degrees celsius

Litter:



[Water Surface/Biodiversity/Corridor:](#)

